

ALERT TOPIC	Damaged Access Cover	ALERT REFERENCE:	CRL 130924
TARGET AUDIENCE:	Regional Managers, Site Managers Site Engineers and Supervisors Other interested people	AUTHORISED BY:	N Roper
DATE OF ISSUE:	Friday 13 September 2024	DISPLAY UNTIL:	March 2024

INTRODUCTION



A Contractor to CRL was recently working within a very restricted and congested work area. To make some space they decided to park one of the forklifts outside of the planned work area on a pedestrian pathway.

Below the pathway was a large service void. The forklift's back wheel overloaded and damaged the service void cover.

REASON FOR ISSUING THIS ALERT

To remind people of the need to thoroughly examine the work area to identify such service ducts and voids and to remain within the planned work areas.

CONCLUSIONS AND DISCUSSION POINTS

Fortunately, there were no injuries. Changes to the planned work often increases the risk of injury or property damage.

