
An incident recently occurred on a CRL site where a small lump of concrete fell to the ground whilst breaking out was taking place on the deck above.



Luckily the concrete fell in a remote grassed area away from people and highways traffic.

Action: Create means to prevent materials and debris from falling or where this is not possible, create exclusion zones below to prevent injury or property damage.

If you have any health and safety issues that you wish to discuss, contact your supervisor, line manager or Safety Advisor.

Remember there must be NO COMPROMISE where health and safety is concerned

